



F16. 2





F16.4

Detect Indications Of Component Portions Of Data Symbol Transform Component Portions Into Transformed Values 138 Estimate Euclidean Norm Of Data Symbol